[23rd July 1962

(8) *Pond near Pappampalayam.*—This refers to formation of pond near Karapalayam Reddipalayam. An estimate for the work is awaited from the Subdivisional Officer. The Executive Engineer (F.P.), Vellore, has reminded the Subdivisional Officer.

(9) *Pond near Kizheripalayam.*—A revised estimate for Rs. 25,300 submitted to the Board of Revenue (F.P.) by the Superintending Engineer (F.P.) is under consideration of the Board of Revenue.

(10) *Pond near Gundumalainaickanur.*—An estimate for Rs. 10,900 was submitted to the Collector. The Collector did not agree to the proposal as it would affect the supplies to the lower down Punjai Dalavoipalayam tank. Hence the proposal has been dropped.

(11) *Pond near Sengalipalayam.*—The estimate is awaited from the Subdivisional Officer and he has been reminded by the Executive Engineer (F.P.), Vellore.

APPENDIX III.

[*Vide* answer to starred question No. 537 on page 9.]

Serial number and name of the scheme. (1)	*Estimated cost.* (2) (RUPEES IN LAKHS.)	*Present stage.* (3)
1 Constuction of an anicut across Pambar in Kilasapuram village in Thirumayam taluk.	2·33	Board has raised certain points for clarification regarding the scheme; the Chief Engineer awaits the Superintending Engineer's report in the matter.
2 Construction of an anicut acrosss Agniar near Pulavanagadu village in Alangudy taluk.	17·20	Remarks of the Board of Revenue on the revenue, financial and Grow More Food aspects of the scheme formulated by the Chief Engineer (Irrigation) are awaited.
3 Construction of an anicut across Korayar near Mullaiyar village in Kolathur taluk.	0·94	The Board of Revenue (Food Production) has been asked to report whether any lower down riparian rights will be affected by the implementation of the scheme; Board's report is awaited.
4 Construction of a head sluice and excavation of a right bank supply channel from the Heldsworth anicut across Vellar in Thirumayam taluk.	4·51	Board has raised certain points for clarification regarding the scheme; the Chief Engineer is awaiting the Superintending Engineer's report in the matter.